
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-103	Smoke	10/14/2008	ADS/TM	S1100_017MH	Dry	Yes	1,863.39

Isolated Pipes


Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11QQ_012G1	S11QQ_012MH	S1100_022MH	35.61451	8
S1100_022G1	S1100_022MH	S1100_001MH	315.3980	8
S1100_017G1	S1100_017MH	S1100_023MH	90.62654	8
S11QQ_004G1	S11QQ_004MH	S1100_017MH	186.7402	8
S1100_001G1	S1100_001MH	S1100_009MH	26.4494	8
S1100_023G1	S1100_023MH	S11QQ_012MH	143.4835	8
S11QQ_008G1	S11QQ_008MH	S11QQ_011MH	109.8257	8
S11QQ_009G1	S11QQ_009MH	S11QQ_001MH	240.4647	8
S11QQ_001G1	S11QQ_001MH	S11QQ_003MH	216.0819	8
S1100_019G1	S1100_019MH	S1100_017MH	168.8024	8
S11QQ_011G1	S11QQ_011MH	S11QQ_004MH	182.1202	8
S11QQ_003G1	S11QQ_003MH	S11QQ_012MH	126.7912	8
S11QQ_006G1	S11QQ_006MH	S11QQ_008MH	20.99595	8

Observations & Photos

Obs_ID S1028-103-OB01
Address 3009 Piedmont Ave
Status Private
Source Cleanout

Location Yard - front
Nearest MH S1100_017MH

Comments Smoke from cleanout in front yard. 3009 Piedmont Ave.



Picture \S1028-103-OB01-P01.jpg

Comments Front of house, 3009 Piedmont Ave.

Obs_ID S1028-103-OB02
Address 3033 Piedmont Ave
Status Private
Source Cleanout

Location Yard - front
Nearest MH S1100_019MH

Comments Smoke from cleanout in front yard. 3033 Piedmont Ave.



Picture \S1028-103-OB02-P01.jpg

Comments Front of house, 3033 Piedmont Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-103	Smoke	10/14/2008	ADS/TM	S1100_017MH	Dry	Yes	1,863.39

Obs_ID S1028-103-OB03

Address 3017 Piedmont Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S1100_017MH

Comments Smoke from cleanout in front yard. 3017 Piedmont Ave.



Picture \S1028-103-OB03-P01.jpg

Comments Front of house, 3017 Piedmont Ave.

Obs_ID S1028-103-OB05

Address 2713 Rosedale St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_004MH

Comments Smoke from cleanout in front yard. 2713 Rosedale St.



Picture \S1028-103-OB05-P01.jpg

Comments Front of house, 2713 Rosedale St.

Obs_ID S1028-103-OB04

Address 2707 Rosedale St


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_004MH

Comments Smoke from cleanout in front yard. 2707 Rosedale St.



Picture \S1028-103-OB04-P01.jpg

Comments Front of house, 2707 Rosedale St.

Obs_ID S1028-103-OB06

Address 2717 Rosedale St


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_004MH

Comments Smoke from cleanout in front yard. 2717 Rosedale St.



Picture \S1028-103-OB06-P01.jpg

Comments Front of house, 2717 Rosedale St.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-103	Smoke	10/14/2008	ADS/TM	S1100_017MH	Dry	Yes	1,863.39

Obs_ID S1028-103-OB07

Address 2737 Rosedale St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_011MH

Comments Smoke from cleanout in front yard. 2737 Rosedale St.



Picture \S1028-103-OB07-P01.jpg

Comments Front of house, 2737 Rosedale St.

Obs_ID S1028-103-OB09

Address 2708 Rosedale St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_004MH

Comments Smoke from cleanout in front yard. 2708 Rosedale St.



Picture \S1028-103-OB09-P01.jpg

Comments Front of house, 2708 Rosedale St.

Obs_ID S1028-103-OB08

Address 2718 Rosedale St


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_004MH

Comments Smoke from cleanout in front yard. 2718 Rosedale St.



Picture \S1028-103-OB08-P01.jpg

Comments Front of house, 2718 Rosedale St.

Obs_ID S1028-103-OB10

Address 2704 Rosedale St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_004MH

Comments Smoke from cleanout in front yard. 2704 Rosedale St.



Picture \S1028-103-OB10-P01.jpg

Comments Front of house, 2704 Rosedale St.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-103	Smoke	10/14/2008	ADS/TM	S1100_017MH	Dry	Yes	1,863.39

Obs_ID S1028-103-OB11

Address 2700 Rosedale St


Status Private

Source Cleanout

Location Yard - front

Nearest MH S1100_017MH

Comments Smoke from cleanout in front yard. 2700 Rosedale St.



Picture \S1028-103-OB11-P01.jpg

Comments Front of house, 2700 Rosedale St.

Obs_ID S1028-103-OB13

Address 2620 Longwood St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S1100_022MH

Comments Smoke from cleanout in front yard. 2620 Longwood St.



Picture \S1028-103-OB13-P01.jpg

Comments Front of house, 2620 Longwood St.

Obs_ID S1028-103-OB12

Address 2624 Longwood St


Status Private

Source Cleanout

Location Yard - front

Nearest MH S1100_022MH

Comments Smoke from cleanout in front yard. 2624 Longwood St.



Picture \S1028-103-OB12-P01.jpg

Comments Front of house, 2624 Longwood St.

Obs_ID S1028-103-OB14

Address 2706 Longwood St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_003MH

Comments Smoke from cleanout in front yard. 2706 Longwood St.



Picture \S1028-103-OB14-P01.jpg

Comments Front of house, 2706 Longwood St.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-103	Smoke	10/14/2008	ADS/TM	S1100_017MH	Dry	Yes	1,863.39

Obs_ID S1028-103-OB15

Address 2710 Longwood St


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_003MH

Comments Smoke from cleanout in front yard. 2710 Longwood St.



Picture \S1028-103-OB15-P01.jpg

Comments Front of house, 2710 Longwood St.

Obs_ID S1028-103-OB16

Address 2716 Longwood St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ_003MH

Comments Smoke from cleanout in front yard. 2716 Longwood St.



Picture \S1028-103-OB16-P01.jpg

Comments Front of house, 2716 Longwood St.

Obs_ID S1028-103-OB17

Address 2714 Longwood St

Status Private

Source Service Lateral

Location Yard - front

Nearest MH S11QQ_003MH

Comments Smoke from service lateral in front yard next to water meter. 2714 Longwood St.



Picture \S1028-103-OB17-P01.jpg

Comments Front of house, 2714 Longwood St.

